



# **LUESA**

## **Customer Service Center & Office Renovation**

**Weekly Update – October 2, 2015**

**Gensler**

**RODGERS | Leeper**

## Meetings & Milestones

### **This Week:**

- ✓ **Wall Framing Continued on 1<sup>st</sup> and 2<sup>nd</sup> Floors**
- ✓ **Demolition of Classroom Tiered Seating In Progress**
- ✓ **MEPF Overhead Rough-In In Progress**
- ✓ **9/29/15 – Subcontractor Meeting**
- ✓ **10/1/15 – O/A/GC Meeting**
- ✓ **Under-Slab Rough In and Pour Back In Progress**

### **Next Week:**

- **Demolition Continues**
- **Wall Framing Continues on 1<sup>st</sup> and 2<sup>nd</sup> Floors**
- **GWB Hanging on 1<sup>st</sup> and 2<sup>nd</sup> Floors**
- **10/6/15 – Subcontractor Meeting**
- **10/8/15 – O/A/GC Meeting**
- **MEPF Overhead Rough-In In Progress**
- **Electrical Rough-In on Upper Floors In Progress**

## Progress Photos



**Electrical Under-Slab Rough-In In Progress**

## Progress Photos



**1<sup>st</sup> Floor Pour Back of Slab Trenches**



## Progress Photos



**1<sup>st</sup> Floor Pour Back of Slab Trenches**

## Progress Photos



**1<sup>st</sup> Floor Wall Framing In Progress**

## Progress Photos



**Level 2 Flooring Demolition In Progress**



## Progress Photos



**Demolition of Tiered Classroom Seating In Progress**



Our  
Passion  
is Building®

**Conclusion of Weekly Update 10/2/15**

**Thank You.**